Preliminary Report on Windstorm Occurred on 4th April, 2015

S.N	Dzongkhag	Gewog	No. of HH	Education Sector	Health Sector/O RC	Cultural Sector	Others public Infrastructure	Human casualty and property damage	Remarks(Relief Support)
1	Dagana	Goshing Khebisa Tsangkha Drujegang Tashiding Dorona Gaserling Tshendagang Khana	60 14 14 4 93 47 35	2 Schools 0 0 1 NFE 11 Schools 0 4 (3 schools and I ECR)	0 0 0 2 (ORC, Staffs Quarter & Kitchen) 0	2 (Lhakhang) 0 0 0 0 0	3 Army Camps 1 RNR Center 0 0 0 3 (Gup Office, RNR office & Meeting Hall) 0	1 Person hospitalised, 1 cow killed	1. The Dzongkhag Administration has deputed the Assessment Team to the affected Sites for detailed assessment. 2. Total of 204 Tarpaulin Sheets are dispatched to be issued to the affected households on need basis. 3. The Dzongkhag Administration is planning to take further course of action once the detailed reports are received from the field. 4. The Dzongkhag Administration has deployed about 15 desuups, 10 Army personnel and around 20 public to help School Managment and Gewog Administration to restore roof of Gangzur PS. Around 100 CGI hseets were issued for the same. 5. The Dzongkhag
	Tot	330	18	2	3	7		5 5	

		Bongo	85	5 schools and 1 NFE center	1 ORC	5 lhakhangs , 1 mani dungkhor & 1 butterlamp house	Roof of Gewog office blown away	Electricity poles damaged, Crops (Wheat,potatoand cardamon)	
		Getana	0	0	0	0	0	One cow killed and two men injured	The Dzongkhag Assessment Teams are at affected sites
		Geling Sampheling	2	2 School 0	0	0	0		assessing the damaged
	Chhukha	Lokchina	3	0	0	0	0		situations.
		Darla	99	12 schools & 1 ECR	0	Lamai Zimchug Damaged; Ihakhang kitchen blown away	Gewog office; RNR office and Research Greeen house damaged	2 persons injured; Electricity poles collapsed and power cut-off;	2. 39 tarpaulin Sheets are dispatched to be issued to the affected households on need basis.
		Phuentsholing	0	1 school	0	0	0		
		Dungna	2	0	0	0	0		
	Tot		191	22	1	10	4		<u> </u>
		Shumar	9	0	0	1	0		Administration has procured 92
		Chongshing	6	0	0	0	0		tarpaulin sheets and dispatched
3	Pemagathsel	Khar	24	0	1(ORC)	0	0		to the affected sites.
		Dungmin Zobel	5	0	0	0	0		2. The Dzongkhag Assessment
		Yurung	2	0	0	0	0		Teams are at affected sites assessing the situation
	Tot		47	0	1	1	0		assessing the situation

								1. T	The Dzongkhag
		Tading	98	4 Schools	1 ORC	1 Chorten	0	Adr	ministration has deputed the
		Ugentse	1	0	0	0	0	Ass	sessment Team with 119
								-	paulin sheets to the affected
						3 (2		Site	
				13 School		Lhakhangs			The Dzongkhag Engineering
		Dorokha	38	Structures	1 BHU	& Duthroe)	0		l has estimated requirement
				1					700 CGI sheets of 8ft, 139m
				Extended					ging, nails other roofing
				Class					terials for restoration of
				Room(EC					ngdhyen Lower Secondary
		samtse	5	R)	0	0	0	2011	nool under Dorokha
4	Samtse	Pemaling	26	0	0	0	0		ngkhag.
									The RBA and Dzongkhag
		Tashichholing	3	0	0	0	0		ms are moving at the schools es for restoration works.
		Denchukha	8	0	0	0	0		The Gewog Administrations
									concultation with Dzongkhag
		Norbugang	11	3 Schools	0	1 Lhakhang	0		Dungkhag Administrations
									re mobilized community
									ople to assisst the restoration
									damaged houses in the
									ected sites.
								** *	The response Teams have
							3 RBP, Two units		tored the damaged structures
		Phuentshopelri	15	2	0	0	of family quarter		Norbugang Lower Secondary
	Tot	205	23	2	5	3			

_	_								asked the Gewog Administration
5	Sarpang	Chudzom	1	0	0	0	0	4 calf killed	to help in re-roofing of the house
	Total		1	0	0	0	0		
		Orong	11	0	0	1 Lhakhang	0		1. The Dzongkhag
		Wangphu	5	0	0	0	0		Administration has dispatched
6	S/jongkhar	Gomdar	2	0	0	0	0		around 45 tarpaulin sheets to the
0	5/jongknar								affected sites.
		Martshala	4	0	0	1 Lhakhang	0		2. The Dzongkhag Assessment
		Phuentshothan							teams are at the affected sites
		g	2	0	0	0	0		assessing the damaged situation
	Total		24	0	0	2	0		
		Ngangla	1	0	0	0	0		1. The Dzongkhag
					1 Staff				Administration has dispatched
7	Zhemgang	Trong	3		Quarter.				around 10 tarpaulin sheets to the
	2	Bjola	1	0	0	0	0		affected sites.
				1 Staff	_	_			2. The Dzongkhag Assessment
		Bardo	1	Quarter	0	0	0		teams are at the affected sites
	Tot		6	1	1	0	0		4 5 4 6 4 6
		Khaling	5	0	0	0	0		1. Total of 10 tarpaulin sheets
8	Trashigang								were dispatched to the affected
		Theimshins	1	0	0	0	0		sites.
		Thrimshing	1	0	0	0	0		2. The Dzongkhag Assessment
	Tot	6	U	0	0	0			

9	Tsirang	Damphu Town Barshong Kilkhorthang Pathaling Rangthaling Mendrelgang Gosaling Sergithang Tsirangtoe	1 9 7 1 1 5 12 2 4	0 0 0 0 0 0	1 Hospital 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0	1 FCB 0 0 0 0 0 0 0 0 0 0 0 0		1. Tenants occupying the house with damaged walls are relocated to a safe place. 2. The Dzongkhag Administration is dispatching around 40 tarpaulin sheets to the affected sites. 3. The team comprising of Dzongkhag and Gewog officials are at sites for further assessment.
	Tot	Pungtenchu al	43	0	0 1	0 0	0 1		assessment.
Thr	omde								
10	Phuenthsolin g Thromde	Phuenthsoling	0	0	0	1 Dratshang Drasha	1 Drungpa's Resident	Roof of Hyundai Showroom blownoff, Fensing of Damchen Petroleum collaped.	The Thromde Office has deputed team to assess the detailed situation and would be taking necessary action based on the team's report.

^{*} As of 8th April , 2015